Capital Improvement Plan 2026

							This is for the 2nd phase of the parking lot repaying project for OHS side of
14231	10	OEC	Oromocto High School (ASD-W)	Building Exterior and Site	Site	Site Improvement	building.
11665	2 F	_	Education Centre (ASD-W)	Mechanical and Electrical Systems	Electrical	Security Systems	Year 4 of 5 - Saltos door Project \$987,853.00.
13903	3 F	EC.	Stanley Consolidated School (ASDW)	Mechanical and Electrical Systems	Heating and Ventalation	Heating System	Replacement of the oil fired boiler, and underground oil tank; to propane fired boiler and installation of all tank(s) and components.
9938	4 F		Royal Road Elementry School (ASDW)	Mechanical and Electrical Systems	Heating and Ventalation	Heating System	DTI Mechanical assessment of the Heat Pump system and loop. Remove existing cooling tower, including dampers, controls and duct connections. Install new closed circuit cooling tower, low leakage dampers with new actuators, duct connections, vibration isolation and controls. To include all electrical connections.
13836	5 F	=EC	New Maryland Elementary School (ASD-W)	Fire Codes	Fire Prevention	Sprinkler System	Dry sprinkler system (branches) are corroding and beginning to leak. Inside of pipe is filling with oxidization. Currently black steel piping. System is due to be replaced. We are experiencing leaks at least a couple times per year and having to call Troy Life in to do repairs. (main lines ONLY were replaced in 2007, branches were not.) It is also noted that some hangers are missing on dry piping causing pipes to be sloped wrong, water collecting inside, not draining to low points.
13993	6 F	EC	McAdam Elementary School (ASD-W)	Mechanical and Electrical Systems	Electrical	Other	Upgrade fire panel and replace devices with new addressable devices. The
2110	7 W	NEC	Centreville Community School (ASD-W)	Building Exterior and Site	Site	Site Improvement	Paving Front area and bus drop off
							Expansion of the parking area as there is limited space for staff to park.
14184	8 W	NEC	Perth-Andover Middle School (ASD-W)	Building Exterior and Site	Exterior Accessibility	Parking and Driveway	Some staff need to park along side of building
11366			Assiniboine Avenue Elementary School (ASD-W) Hubbard Elementary School (ASD-W)	Building Exterior and Site Building Exterior and Site	Building Envelope Building Envelope	Exterior Windows Other	Some windows are starting to leak into interior walls. (Update Aug 28th, 2024) Back side of School completed!! Project recommended to continue in 2025 This is a project to remove all the stucco from exterior walls and replace with metal siding. Approximately 450 sqm.
			Carleton North High School (ASD-W)	Building Exterior and Site	Building Envelope	Other	Eintel and Widow replacement. Most windows have broken seals, and a majority of lintels ate rusted almost all the way through. A structural study was completed and there is a risk of wall deterioration causing multiple problems in the future. Propose Phase One to replace Rusted Lintels where area is at most risk (East side of Building)
							© ym floor will need to be replaced. Asbestos tiles will need to be removed,
14260	12 F	-EC	Upper Miramichi Elementary School (ASD-W)	Building Interior and Additions	Interior Alterations and Renovations	Gym	and lines put back.
14251	13 F	EC	Keswick Ridge School (ASD-W)	Building Exterior and Site	Building Envelope	Other	Septic Field needs to be looked at. A lot of trees and shrubs growing may cause problems for the septic field to work correctly.
14157	14 F	EC	Kingsclear Community School (ASD-W)	Building Exterior and Site	Building Envelope	Other	Remove and replace 32 windows at upper and ground level and install new vinyl windows in existing frames. If we are intending to add ventilation units to this school these windows will need to be repaired before or during the installation. The window glass is now rotting out of the frames.

Capital Improvement Plan 2026

							Replace underground oil tank. Replace boilers. Could go with new propane
							heating system. Replace piping in boiler room. Also, library side of school need new zone valves and thermostats. Need DTI to review costs for
11466	15	FEC	Doaktown Elementary School (ASD-W)	Mechanical and Electrical Systems	Heating and Ventilation	Heating System	accuracy.
14254	_		Montgomery Street Elementary School (ASD-W)	Building Exterior and Site	Site	Drainage	Drainage in the parking lot and also a repaving of the surface.
			, , , ,	, and the second			
							The rockface panels on the exterior of the school is falling off and is not
							protecting from the weather anymore. Fear of water intrusion into school
14253	17	FEC	Liverpool Street Elementary School (ASD-W)	Building Exterior and Site	Building Envelope	Other	causing damage and possibility of mold in the interior of school.
							Renovate 2 girls' washrooms new wing -PH3 49 sqm. NOTE: Estimated costs
							updated in Aug'11. Update-Sept 2024 they are currently renovating the top
8270	18	OEC	Harold Peterson Middle School (ASD-W)	Building Interior and Additions	Interior Alterations and Renovations	Washrooms	floor girls' washroom. Lower level is next.
							Fire Panel needs to be replaced. Old out of date equipment, First generation
							Edwards alarm Panel. You cannot get replacement parts for this type of alarm
14228	19	FEC	McAdam Elementary School (ASD-W)	Fire Codes	Fire Prevention	Fire Alarms	panel.
14250	20	FEC	George Street Middle School (ASD-W)	Building Interior and Additions	Interior Finishes	Other	Floors are asbestos and in rough shape. Cracking and lifting.
							The septic system at Keswick Valley is quite old and should be redesigned
							and rebuilt. Concrete cover to pump station is decaying. Pumps station
13960	21	FEC	Keswick Valley Memorial School (ASD-W)	Mechanical and Electrical Systems	Water Supply and Sewer	Sanitary Sewer Systems	design is not ideal due to pumps plugging up regularly and needing replaced.
							Repave parking lot. Concrete replacement (where heaved) in front of main
8099	22	FEC	Harvey High School (ASD-W)	Building Exterior and Site	Site	Site Improvement	entrance
							The wooden gym floor needs to be sanded and refinished, This means that
14235	23	FEC	Montgomery Street Elementary School (ASD-W)	Building Interior and Additions	Interior Alterations and Renovations	Other	the lines will need to be done also which is a major portion of the cost.
							A structural study was completed in 2025 on the Woodstock Education
4 40 40		\.\.\.	Education Control (ACD M)	Duritation a Fortunian and Oite	0:4-	0:1	Centre, and it was determined that the main floor needed to be upgraded to
14243	24	WEC	Education Centre (ASD-W)	Building Exterior and Site	Site	Site Improvement	accomidate the weight load for office space
10016	O.F.	050	Ridgeview Middle School (ASD-W)	Building Exterior and Site	Site	Cita Improvement	Repave and install new curbs. Staff entrance all the way around to the shop.
10216	25	UEC	Ridgeview Middle School (ASD-W)	Building Exterior and Site	Site	Site Improvement	This does not include the staff parking area.
							Principal deems office area a safety issue and wants it moved to another
14000	200	050	Chinman Flamentan (School (ASD M))	Duilding Interior and Additions	Interior Alterations and Denovations	Offices	area of the school. The cost will be the new office renovation along with the
14069	20	UEC	Chipman Elementary School (ASD-W)	Building Interior and Additions	Interior Alterations and Renovations	Offices	movement of the PA system etc. Parking let needs repoving and drainage leaked at We did some ditabing to
							Parking lot needs repaving and drainage looked at. We did some ditching to prevent water from running across the parking lot in winter causing it to be
1/050	27	EEC	Kingsclear Community School (ASD-W)	Building Exterior and Site	Site	Drainage	slippery. the water is not running across the parking lot but still needs to be looked at.
14232				Mechanical and Electrical Systems	Electrical	Electrical Maintenance	The high voltage switch gear needs to be serviced.
14237	20	110	Mackawic Filadic School (ASD-W)	r rechanicat and Electrical Systems	Licetifeat	Liectrical Planiferiance	©omplete renovation of female locker/shower rooms. Boys side complete
8305	20	OEC	Oromocto High School (ASD-W)	Building Interior and Additions	Interior Alterations and Renovations	Changing Room	Sept 2024
			Royal Road Elementary School (ASD-W)	Mechanical and Electrical Systems	Electrical	Other	Eighting in the gym needs improvement.
17207	00		mojat noda Etementary ochoot (nob W)	1 100 nameut and Etectrical Dysterns	Licotriout	Table	= 6 min 6 min 6 6 min needs improvement.

Total Budget Requested